

2580 East Philadelphia Street, Unit C, Ontario, California, 91761 USA 909.930.3600 | Toll Free 877.374.5521 | Fax 909.930.3323 dsi-hums.com

HUMS FACT SHEET

ATTENTION CUSTOMER BUSINESS MANAGERS, AUTHORIZED DISTRIBUTORS, AND OPERATORS

STC No.: SR01970NY-D STC Holder: Honeywell International Inc 23500 W. 105 th Street Olathe, KS 66061		Agusta A109
STC Issue Date: STC Reissue Date: Applicable to: HUMS Model:	Aug 2005 Jun 2009 A109E VXP HUMS	

NOTE:

SUMMARY:

Honeywell has developed an automated vibration monitoring system for the Agusta A109 helicopter. The VXP Kit provides the Agusta A109 Helicopter a comprehensive rotor, engine and drive train system vibration monitoring capability.

The VXP Kit is designed to conduct routine vibration management functions, with no changes required in the mandatory maintenance functions of the maintenance manual. The system utilizes its vibration monitoring capability to make discretionary rotor and balance adjustments. No pilot interface is required during flight operations. The Rotor Track & Balance (RT&B) solution generated on-board and downloaded to the PC ground station for display to the maintenance personnel.

The on-board system automatically acquires and processes sensor data, continuously monitors real-time condition and health indices, records aircraft intelligent information and saves data for post-flight analysis in the ground station.

The systems provides:

- Rotor Track & Balance solution.
- Engine and drive train vibration monitoring.
- Real time, continuous monitoring of engine and dynamic component health and usage without human intervention.
- Operational usage accumulation and recording.
- Integrated and automated aircraft maintenance functions to eliminate the need for ground support equipment.

Software provided with the ground station assists maintenance personnel to perform aircraft maintenance and troubleshooting. For QA personnel, the software allows the review of the aircraft condition and health status, perform analysis, trending, and analysis to generate maintenance action (work order).

Operators are utilizing the information from the VXP to enhance safety, reduce maintenance costs, and increase aircraft availability.



Part Number	Qtv	Description
915-17218	1	A109 Installation Kit
0.02.0		71700 motamation rit
901-17330	1	VXP Display Unit
901-11800-3	1	Optical Tracker
904-15267	1	Tracker Bracket (A-109 A/A11/C/K/MAX)
903-13420	1	Tracker Bracket (A-109 A/A11/C/BA/MAX/K)
906-16595	1	Tracker Bracket Main Rotor
	meters and	d 2 Tachometers/Photocells as shown below.
	C:	
NSTALL LOCATION	S:	
		HANGER GEARING No. 1 HANGER SCARING No. 2 ACCELEROHERS AC
NSTALL LOCATION OIL COOLER FAN S ACCOLUMNICS	UPPORT — HAT	ACCELEROHETER / / ACCELEROHETER
OIL COOLER FAN S	UPPORT HAI	MCCS_EROHETER / ACCSLEROHETER NOTICE MARKET No. 3 MARKET NO. 4,5,5 AND 7
OH, COOLER FAN S ACCOLERMETES HA IS FOR TRACHIS ACCOLERO	MPORT HAI MACHINE SIGN METERS	MCCS_EROHETER / ACCSLEROHETER NOTICE MARKET No. 3 MARKET NO. 4,5,5 AND 7
OIL COOLER FAN S ACCOLEROMETES THE RESEARCH THE RESEARCH FOR THE RESEARCH	MPORT HAI MACHINE SIGN METERS	IN POTOR INDICATE ACCELERATION No. 1 HAMER No. 4, 5,5,440 7 RADELERATE REPORT OF ACCELERATION No. 1 TABLE ROLL FOR THE POTOR NAME ACCELERATE THE P
OIL COOLER FAN S ACOLERMETERS HA IN ROT TRAGENIS ACORLEGO BU PAN 1/6714.	PPORT HAI	IN POTOR INDICATE ACCELERATION No. 1 HAMER No. 4, 5,5,440 7 RADELERATE REPORT OF ACCELERATION No. 1 TABLE ROLL FOR THE POTOR NAME ACCELERATE THE P
OIL COOLER FAN S ACOLEROMETES HATELENIN TAKASHIS ACOLERO DI PAN	PPORT HAI	N POTOR INDICATE ACCELERATION No. 1 HAMER Nos. 4,55 AND 7 BENTILE ACCELERATION No. 1 BENTILE ACCELERATION NO. 1 BENTILE ACCELERATION NO. 1 IAIL ROUP GENERAL ACCELERATION NO. 1 IAIL ROUP ROUP NO. 1 IAIL ROUP
OH, COOLER FAN S ACOL EXPERIES MI IN RUI TRACKIS ACOL FRO BY PAN INSTAL OPTICAL TRACKER DONNESSE	PPORT HAI	N POTOR INSIDE ACCELERATED ACCELERATED No. 1 RAMERS DESCRIPTION No. 1 RAMERS No. 4, 5,5,440 7 REMAINS DESCRIPTION NO. 1 RAMERS No. 4, 5,5,440 7 REMAINS DESCRIPTION NO. 1 TABLE BOTCH NAC. PICKEP 1AM. 8070P GEARMON ACCELERATED NAC. REMAINS DESCRIPTION NAC. REMAINS
OIL COOLER IAN S ACOL DEPETIOS IN IN RIT TRACIST OPTICAL TRADER DONNESSE	PPORT HAI	NO POTOR INDICATE RADIEL ROPETER ACCELERATE TO No. 1 RADIEL ROPETER ACCELERATE TO NO. 1 RADIEL ROPETER ACCELERATE TO NO. 1 RADIEL ROPETER TABLE ROTOR HAS. PICKER TABLE ROTOR HAS. PICKER TABLE ROTOR HAS. PICKER TABLE ROTOR GRAPHER TO PROCESSOR TO PROCESSOR TO PROCESSOR
OIL COOLER IAN S ACOLERMETES HIS RIT TRACKS ACOLERO BY PAR HIGHAL DPTICAL TRADER	PPORT HAI MAN MAN MAN MAN MAN MAN MAN MAN MAN MAN	N POTOR INSIDE ACCELERATED ACCELERATED No. 1 RAMERS DESCRIPTION No. 1 RAMERS No. 4, 5,5,440 7 REMAINS DESCRIPTION NO. 1 RAMERS No. 4, 5,5,440 7 REMAINS DESCRIPTION NO. 1 TABLE BOTCH NAC. PICKEP 1AM. 8070P GEARMON ACCELERATED NAC. REMAINS DESCRIPTION NAC. REMAINS
OIL COOLER FAN S ACCOLEROPTIOS HIS RIT TRACKSIS ACCOLERO BY PAN HIGHAL DONNESSES	PPORT HAI MAN MAN MAN MAN MAN MAN MAN MAN MAN MAN	NOTICE PROPERTY ACCULABOLIST No. 1 RANGES No. 4, 5,5,400 7 REMAIN ACCULABOLIST NO. 1 RANGES No. 4, 5,5,400 7 REMAIN ACCULABOLIST NO. 1 RANGES No. 4, 5,5,400 7 RANGES No. 4, 5,5,5,400 7 RANGES No. 4, 5,5,400 7 RANG

For technical support and additional information, please contact:

Brian C. Hatcher

Phone: (909) 930-3600 Ext. 222

Cell: +1-949-690-2914

brian.hatcher@dsi-hums.com

Neil Seamon

Phone: (909) 930-3600 Ext. 228

Cell: +1-949-232-3760

neil.seamon@dsi-hums.com