



2580 East Philadelphia Street, Unit C, Ontario, California, 91761 USA
 909.930.3600 | Toll Free 877.374.5521 | Fax 909.930.3323
 dsi-hums.com

HUMS FACT SHEET

*ATTENTION CUSTOMER BUSINESS MANAGERS,
 AUTHORIZED DISTRIBUTORS, AND OPERATORS*

STC No.: SR02430NY-D		Sikorsky S-76C
STC Holder: Sikorsky Global Helicopters, Inc. 110 E Stewart Huston Drive Coatesville, PA 19320		
STC Issue Date:	Aug 2007	
STC Reissue Date:	Oct 2011	
Applicable to:	S-76C	
HUMS Model:	EVXP HUMS	
NOTE: Data contained within this Factsheet is applicable to S-76C models SN 760511 and subsequent		
SUMMARY: This STC allows for the replacement of the Honeywell VXP installed under STC SR01135NY-D with Honeywell's Enhanced VXP (EVXP). The EVXP provides the S-76C helicopter a comprehensive rotor, engine and drivetrain system vibration monitoring capability.		
Functions include: <ul style="list-style-type: none"> • Main and Tail Rotor Track & Balance solution • Data Management • Real time, continuous monitoring of engine and dynamic component health and usage without human intervention • Operational usage accumulation and Helicopter Operational Monitoring Program (HOMP) parameters recording • Operational usage recorded for: engine and air data parameter recording, engine cycle counters, engine start/stops, engine time, takeoff and landings, and rotor on time • Integrated and automated aircraft maintenance functions to eliminate the need for ground support equipment 		
The EVXP allows for the collection of parameters from the aircraft's ARINC 429 data bus. The EVXP also interfaces to the automatic flight control system, air data and attitude systems, instrument display system, and the digital engine controls.		
Software provided with the ground station assists maintenance personnel to perform aircraft maintenance and troubleshooting. For QA personnel, the software allows the review of the aircraft condition and health status, perform analysis, trending, and analysis to generate maintenance action (work order).		
Operators are utilizing the information from the VXP to enhance safety, reduce maintenance costs, and increase aircraft availability.		



2580 East Philadelphia Street, Unit C, Ontario, California, 91761 USA
 909.930.3600 | Toll Free 877.374.5521 | Fax 909.930.3323
 dsi-hums.com


MAJOR COMPONENT PART NUMBERS:

Part Number	Qty	Description
915-17575	1	S-76C EVXP Wiring Kit
915-17942	1	VXP to EVXP Conversion Kit (S76C post SN 511)
901-17700	1	EVXP Data Acquisition Unit
915-18202	1	Ground Kit
901-11800-3	1	FasTrak Optical Tracker

SENSORS:

17 Vibration Accelerometers and 2 Tachometers/Photocells as shown below

INSTALL LOCATIONS:



OPTIONS:

For technical support and additional information, please contact:

Brian C. Hatcher
 Phone: (909) 930-3600 Ext. 222
 Cell: +1-949-690-2914
brian.hatcher@dsi-hums.com

Neil Seamon
 Phone: (909) 930-3600 Ext. 228
 Cell: +1-949-232-3760
neil.seamon@dsi-hums.com